

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,889,284 B1
DATED : May 3, 2005
INVENTOR(S) : Nizar et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4,

Line 67, delete "1" and insert -- =1 --.

Column 6,

Line 18, after "row.", insert -- MA[7.0]=Byte Masks for DQA bus. --.

Column 8,


Line 42, after "generated", insert -- by --.

Column 10,

Line 43, delete "representative" and insert -- responsive --.

Signed and Sealed this

Sixteenth Day of August, 2005



JON W. DUDAS
Director of the United States Patent and Trademark Office